

Juniper Flat Rural Fire

Juniper Flat RFPD

Wasc_fir03A

Building Type Fire - RFPD	County Wasco	
Street 80501 HWY 216		
City Maupin	State OR	Zip 97037
Latitude 45.12744	Longitude 121.25559	
Tracking Code New Building	Inspection Date 8/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Juniper Flat Rural Fire

Final RVS Score

Final Type	Final Score
S3	3.8

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Juniper Flat Rural Fire

Wasc_fir03A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
N	Building Name	SW	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Juniper Flat Rural Fire

Juniper Flat RFPD

Wasc_fir03B

Building Type Fire - RFPD	County Wasco									
Street 80501 HWY 216										
City Maupin	State OR	Zip 97037								
Latitude 45.12706	Longitude 121.25588									
Tracking Code New Building	Inspection Date 8/25/2006									
Seismicity Zone: Moderate										
FEMA 154 Rapid Visual Screening Score Card										
	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.8	0	0	0	0	0	0	0	3.8
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Juniper Flat Rural Fire

Final RVS Score

Final Type S3	Final Score 3.8
------------------	--------------------

FEMA-154 Collapse Potential

Low (<1%)







OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Juniper Flat Rural Fire

Wasc_fir03B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	Building Name	N	Primary Structural Type
			
		NE	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries