

OSP

Oregon State Police

Wasc_pol01A

Building Type Police - State	County Wasco	
Street 3313 Bret Clodfelter Way		
City The Dalles	State OR	Zip 97058
Latitude 45.60631	Longitude 121.13175	
Tracking Code RVS in 2006	Inspection Date 8/24/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	-0.5	0	0	0	0	0	3.1
Secondary	W1	5.2	0	-0.5	0	0	0	0	0	4.7
Tertiary		0	0	0	0	0	0	0	0	0

OSP

Final RVS Score

Final Type	Final Score
C2	3.1


FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:Other (Adjacent Build/Entity)		None	
Out of Plane Lateral-Force-Resistance Elements		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE	Plan Irregularity Secondary	S	Building Name
			
S	Building Name	S	Building Name
			
SW	Elevation View addn end		

