

The Dalles Middle School

Wasc_sch02A

North Wasco County SD 21

| | | | |
|----------------|-------|-----------------|--|
| Building Type | | County | |
| School | | Wasco | |
| Street | | | |
| 1100 E 12th St | | | |
| City | State | Zip | |
| The Dalles | OR | 97058 | |
| Latitude | | Longitude | |
| 45.59242 | | 121.17571 | |
| Tracking Code | | Inspection Date | |
| New Building | | 9/15/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

The Dalles Middle School

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 658 | | 2002 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 99000 | | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| | |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| | |
| | |
| | |