

Colonel Wright Elementary School

North Wasco County SD 21

Wasc_sch08A

Building Type	County	
School	Wasco	
Street		
610 W 14th St		
City	State	Zip
The Dalles	OR	97058
Latitude	Longitude	
45.59759	121.1982	
Tracking Code	Inspection Date	
RVS in 2006	8/24/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	0	0	-0.4	0	-0.8	0	0	2.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Colonel Wright Elementary School

Final RVS Score

Final Type	Final Score
C2	2.4

FEMA-154 Collapse Potential

Low (<1%)



Colonel Wright Elementary School

Wasc_sch08A

Enrollment 350	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1920	Est. Decade Built 1920
Total Area (square ft) 34109	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: Ornamental Hazard Over Exit Unreinforced Chimneys None		Poor Conditions None None None	
			
S Falling Hazard	S Elevation View	W	Elevation View



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Colonel Wright Elementary School

North Wasco County SD 21

Wasc_sch08B

Building Type	County	
School	Wasco	
Street		
610 W 14th St		
City	State	Zip
The Dalles	OR	97058
Latitude	Longitude	
45.59723	121.19787	
Tracking Code	Inspection Date	
RVS in 2006	8/24/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	-3	-0.5	0	0	-0.8	0	0	0.5
Secondary	URM	3.4	-1.5	-0.5	0	0	-0.4	0	0	1
Tertiary	RM1	3.6	-2	-0.5	0	0	-0.8	0	0	0.3

Colonel Wright Elementary School

Final RVS Score

Final Type	Final Score
RM1	0.3

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Colonel Wright Elementary School

Wasc_sch08B

Enrollment 350	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1950
Total Area (square ft) 34109	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes Building On Hill or Sloped Site None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
			
E Vertical Irregularity Primary		E Other wall detail	NE Pounding Potential
			
NW Secondary Structural Type wall detail		NW Vertical Irregularity Primary	SW Elevation View
		S Pounding Potential	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Colonel Wright Elementary School

North Wasco County SD 21

Wasc_sch08C

Building Type	County
School	Wasco
Street	
610 W 14th St	
City	State Zip
The Dalles	OR 97058
Latitude	Longitude
45.59716	121.19846
Tracking Code	Inspection Date
RVS in 2006	8/24/2006



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	4.8	0	0	0	0	-0.8	0	0	4
Secondary	URM	3.4	0	0	0	0	-0.4	0	0	3
Tertiary		0	0	0	0	0	0	0	0	0

Colonel Wright Elementary School

Final RVS Score

Final Type	Final Score
URM	3

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Colonel Wright Elementary School

Wasc_sch08C

Enrollment 350	Year Built (Field Verified) 1924	Year Built (Alt. Source) 1924	Est. Decade Built 1950
Total Area (square ft) 34109	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities None None None		Vertical Irregularities None None None	
Falling Hazards Other: Ornamental Hazard Over Exit None None		Poor Conditions None None None	
 NW Secondary Structural Type		 N Falling Hazard	
 NW Primary Structural Type corr walls w clerestory		 W Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries