

Maupin Elementary School

South Wasco County SD 1

Wasc_sch10A

Building Type	County	
School	Wasco	
Street		
308 Deschutes Ave		
City	State	Zip
Maupin	OR	97037
Latitude	Longitude	
45.17665	121.07871	
Tracking Code	Inspection Date	
RVS in 2006	8/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	0	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Maupin Elementary School

Final RVS Score

Final Type	Final Score
C2	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Maupin Elementary School

Wasc_sch10A

Enrollment 123	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1930
Total Area (square ft) 31691	Number of Stories 2	Basement	Pounding Potential Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Reentrant Corners: Other (Adjacent Build/Entity)		Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity)	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
None		None	
None		None	
			
W Falling Hazard	E Vertical Irregularity Primary	S Elevation View	
			
			
S General Site conn to c			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Maupin Elementary School

South Wasco County SD 1

Wasc_sch10B

Building Type School	County Wasco	
Street 308 Deschutes Ave		
City Maupin	State OR	Zip 97037
Latitude 45.17689	Longitude 121.07885	
Tracking Code RVS in 2006	Inspection Date 8/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	3.6	-2	-0.5	-0.4	0	0	0	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Maupin Elementary School

Final RVS Score

Final Type	Final Score
C2	0.7

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Maupin Elementary School

Wasc_sch10B

Enrollment 123	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1930
Total Area (square ft) 31691	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
 NW Elevation View		 NE Primary Structural Type form marks	 NE Elevation View
 SE General Site conn to a			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Maupin Elementary School

South Wasco County SD 1

Wasc_sch10C

Building Type	County	
School	Wasco	
Street		
308 Deschutes Ave		
City	State	Zip
Maupin	OR	97037
Latitude	Longitude	
45.17646	121.0789	
Tracking Code	Inspection Date	
RVS in 2006	8/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	-2	-0.5	0	0	0	0	0	1.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Maupin Elementary School

Final RVS Score

Final Type	Final Score
RM1	1.1

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Maupin Elementary School

Wasc_sch10C

Enrollment 123	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1970
Total Area (square ft) 31691	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: Single Change (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
SE Elevation View		SW Elevation View	

Maupin Elementary School

South Wasco County SD 1

Wasc_sch10D

Building Type School	County Wasco	
Street 308 Deschutes Ave		
City Maupin	State OR	Zip 97037
Latitude 45.17622	Longitude 121.07931	
Tracking Code RVS in 2006	Inspection Date 8/25/2006	



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	3.6	0	0	0	0	0	0	0	3.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Maupin Elementary School

Final RVS Score

Final Type	Final Score
RM1	3.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Maupin Elementary School

Wasc_sch10D

Enrollment 123	Year Built (Field Verified) 1930	Year Built (Alt. Source) 1930	Est. Decade Built 1970		
Total Area (square ft) 31691	Number of Stories 1	Basement	Pounding Potential No		
Plan Irregularities		Vertical Irregularities			
Out of Plane Lateral-Force-Resistance Elements None		None			
None		None			
Falling Hazards		Poor Conditions			
None		None			
None		None			
None		None			
	SW Primary Structural Type		NW Elevation View		NW Plan Irregularity Primary
	NE Elevation View		SE Plan Irregularity Primary		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries