

Rock Creek - Building 5

Wash_coc03A

Portland CC

Building Type		County	
Community_College		Washington	
Street			
17705 NW Springville Rd			
City	State	Zip	
Portland	OR	97229	
Latitude		Longitude	
45.5666		122.85959	
Tracking Code		Inspection Date	
Miller 2004-05		8/31/2005	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	C2	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Rock Creek - Building 5

Final RVS Score

Final Type


Final Score

RM1

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1982	1982	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
47067	2	No	No

Plan Irregularities	Vertical Irregularities
Yes: Unknown	Yes: Unknown

Falling Hazards	Poor Conditions
None	
None	
None	

