

Rock Creek - Building 7

Wash_coc05A

Portland CC

Building Type		County	
<input type="text" value="Community_College"/>		<input type="text" value="Washington"/>	
Street			
<input type="text" value="17705 NW Springville Rd"/>			
City	State	Zip	
<input type="text" value="Portland"/>	<input type="text" value="OR"/>	<input type="text" value="97229"/>	
Latitude		Longitude	
<input type="text" value="45.56635"/>		<input type="text" value="122.86145"/>	
Tracking Code		Inspection Date	
<input type="text" value="New Building"/>		<input type="text" value="3/1/2007"/>	

Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Rock Creek - Building 7


Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1996	1996	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
62500	2	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions