

TVF & R - Station 53 Progress

Tualatin Valley F&R

Wash_fir06A

Building Type Fire - RFPD	County Washington	
Street 8480 Sw Scholls Ferry Rd		
City Beaverton	State OR	Zip 97008
Latitude 45.45868	Longitude 122.78096	
Tracking Code To be Re-built	Inspection Date 6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 53 Progress

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

Low (<1%)




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

TVF & R - Station 53 Progress

Wash_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1966	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
8152	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
Torsion: Eccentric Stiffness		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
W	Building Name	S	Primary Structural Type
			
W	General Site	W	General Site
			
E	General Site		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries