

TVF & R - Station 69 Cooper Mtn

Tualatin Valley F&R

Wash_fir09A

Building Type Fire - RFPD	County Washington	
Street 9940 SW 175th		
City Aloha	State OR	Zip 97007
Latitude 45.4483	Longitude 122.85628	
Tracking Code To be Retrofit	Inspection Date 6/28/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	0	0	1.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 69 Cooper Mtn

Final RVS Score

Final Type	Final Score
RM1	1.3

FEMA-154 Collapse Potential

Low (<1%)



Oregon Geology

TVF & R - Station 69 Cooper Mtn

Wash_fir09A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1981	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
5971	1	No	No
Plan Irregularities		Vertical Irregularities	
Lateral-Force-Resistance in One Direction Only		Steps in Elevation View: 2 to 3 Changes	
Reentrant Corners: Other		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
None		None	
None		None	
			
W Plan Irregularity Primary		W Building Name	
			
		SW General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries