

TVF & R - Station 64 Rock Creek/Somerset

Wash_fir10A

Tualatin Valley F&R

Building Type		County	
Fire - RFPD		Washington	
Street			
3355 Nw 185th			
City	State	Zip	
Portland	OR	97229	
Latitude		Longitude	
45.54332		122.86826	
Tracking Code		Inspection Date	
To be Retrofit		6/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 64 Rock Creek/Somerset

Final RVS Score

Final Type

Final Score

RM1

0.9

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries


TVF & R - Station 64 Rock Creek/Somerset

Wash_fir10A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7444	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: L shaped (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
Lateral-Force-Resistance in One Direction Only	None
None	None

Falling Hazards	Poor Conditions
Other: General	None
None	None
None	None



NW Primary Structural Type



NE General Site



NE Building Name

SW General Site
Tower is RM1

TVF & R - Station 64 Rock Creek/Somerset

Wash_fir10B

Tualatin Valley F&R

Building Type		County	
Fire - RFPD		Washington	
Street			
3355 Nw 185th			
City	State	Zip	
Portland	OR	97229	
Latitude		Longitude	
45.54321		122.86821	
Tracking Code		Inspection Date	
To be Retrofit		6/30/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	-2.5	-0.5	0	0	0	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 64 Rock Creek/Somerset

Final RVS Score

Final Type

Final Score

W1

1.4

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1970	1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7444	2	Yes	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Building On Hill or Sloped Site
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None




S Plan Irregularity Primary



SE General Site



NE Plan Irregularity Secondary



NE Plan Irregularity Secondary