

TVF & R - Station 61 Butner Rd

Tualatin Valley F&R

Wash_fir11A

Building Type

Fire - RFPD

County

Washington

Street

13730 Sw Butner Rd

City

Beaverton

State

OR

Zip

97005

Latitude

45.51389

Longitude

122.81845

Tracking Code

New Building

Inspection Date

9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 61 Butner Rd

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Low (<1%)

No Planview Available



OregonGeology

 Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
 Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		2000	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
7600		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions