

TVF & R - Station 67 Farmington

Tualatin Valley F&R

Wash_fir12A

Building Type		County	
Fire - RFPD		Washington	
Street			
13810 Sw Farmington Rd			
City	State	Zip	
Beaverton	OR	97005	
Latitude		Longitude	
45.48649		122.81903	
Tracking Code		Inspection Date	
New Building		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 67 Farmington

Final RVS Score

Final Type

Final Score

--	--

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1998	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
11900		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions