

Building Type Fire - RFPD	County Washington	
Street 13900 Sw Brockman Rd		
City Beaverton	State OR	Zip 97005
Latitude 45.45452	Longitude 122.82039	
Tracking Code To be Retrofit	Inspection Date 9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF &amp; R - Station 66 South Beaverton

## Final RVS Score

Final Type

Final Score

## FEMA-154 Collapse Potential

Low (&lt;1%)

No  
Planview  
Available



Oregon Geology

# TVF & R - Station 66 South Beaverton

Wash\_fir16A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	1974	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
4582	<input type="text"/>	No	No
Plan Irregularities		Vertical Irregularities	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
Falling Hazards		Poor Conditions	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	
<input type="text"/>		<input type="text"/>	