

TVF & R - Station 51 Tigard

Tualatin Valley F&R

Wash_fir17A

Building Type Fire - RFPD	County Washington	
Street 8935 SW Burnham St		
City Tigard	State OR	Zip 97223
Latitude 45.42763	Longitude 122.76823	
Tracking Code To be Retrofit	Inspection Date 6/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 51 Tigard

Final RVS Score

Final Type	Final Score
RM1	0.9

FEMA-154 Collapse Potential

Low (<1%)



Oregon Geology

TVF & R - Station 51 Tigard

Wash_fir17A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1993	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
9664	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: Other		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Building Name	S	Plan Irregularity Primary
			
SW	Primary Structural Type		
			
S	Falling Hazard		
NE	Elevation View		



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries