

Banks FPD Timber Station

Banks RFPD

Building Type Fire - RFPD	County Washington	
Street 60900 NW Cochran Rd		
City Timber	State OR	Zip 97144
Latitude 45.71581	Longitude 123.3009	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	S3	3.2	0	-0.5	0	0	-0.4	0	0	2.3
Secondary	W2	3.8	0	-0.5	0	0	-0.4	0	0	2.9
Tertiary		0	0	0	0	0	0	0	0	0

Banks FPD Timber Station

Final RVS Score

Final Type	Final Score
S3	2.3

FEMA-154 Collapse Potential

Low (<1%)



Oregon Geology

Banks FPD Timber Station

Wash_fir32A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1970
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
W	General Site	W	Vertical Irregularity Primary
			
NW	Building Name	N	General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries