

TVF & R - Station 33 Sherwood

Wash_fir33A

Tualatin Valley F&R

Building Type		County	
Fire - RFPD		Washington	
Street			
15440 SW Oregon St			
City	State	Zip	
Sherwood	OR	97140	
Latitude		Longitude	
45.35862		122.8357	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

TVF & R - Station 33 Sherwood

Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
<input type="text"/>	<input type="text"/>	1970	<input type="text"/>
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
6404	<input type="text"/>	No	No

Plan Irregularities	Vertical Irregularities
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

Falling Hazards	Poor Conditions
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>

