

# Hillsboro Police Dept

City of Hillsboro

Wash\_pol01A

|                                |                              |              |
|--------------------------------|------------------------------|--------------|
| Building Type<br>Police - City | County<br>Washington         |              |
| Street<br>250 SE 10th Ave      |                              |              |
| City<br>Hillsboro              | State<br>OR                  | Zip<br>97213 |
| Latitude<br>45.52083           | Longitude<br>122.97328       |              |
| Tracking Code<br>RVS in 2006   | Inspection Date<br>7/13/2006 |              |

Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

|           | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary   | RM1  | 2.8         | 0          | 0          | 0        | 0          | 0      | -0.6   | 0      | 2.2       |
| Secondary |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |
| Tertiary  |      | 0           | 0          | 0          | 0        | 0          | 0      | 0      | 0      | 0         |

Hillsboro Police Dept

## Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1        | 2.2         |

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

|                        |                             |                          |                    |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment             | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built  |
|                        |                             |                          | 1970               |
| Total Area (square ft) | Number of Stories           | Basement                 | Pounding Potential |
|                        | 1                           | No                       | No                 |
| Plan Irregularities    |                             | Vertical Irregularities  |                    |
| None                   |                             | None                     |                    |
| None                   |                             | None                     |                    |
| None                   |                             | None                     |                    |
| Falling Hazards        |                             | Poor Conditions          |                    |
| None                   |                             | None                     |                    |
| None                   |                             | None                     |                    |
| None                   |                             | None                     |                    |