

# North Plains Police Dept

City of North Plains

Wash\_pol05A

Building Type Police - City	County Washington	
Street 31360 Nw Commercial St		
City North Plains	State OR	Zip 97133
Latitude 45.5974	Longitude 122.99959	
Tracking Code New Building	Inspection Date 7/5/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Plains Police Dept

## Final RVS Score

Final Type	Final Score
RM1	1.7

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Plains Police Dept

Wash\_pol05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
		1995	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
E	Building Name	NE	Primary Structural Type



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Plains Police Dept

City of North Plains

Wash\_pol05B

Building Type Police - City	County Washington	
Street 31360 Nw Commercial St		
City North Plains	State OR	Zip 97133
Latitude 45.59733	Longitude 122.99961	
Tracking Code New Building	Inspection Date 7/5/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	-0.5	0	2.4	0	0	0	6.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

North Plains Police Dept

## Final RVS Score

Final Type	Final Score
W1	6.3

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# North Plains Police Dept

Wash\_pol05B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1995	1995	1990
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	Yes
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:L shaped (Adjacent Build/Entity)		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW General Site Back of Bldg B		NW Plan Irregularity Primary Bldg A is in front left bldg B is back right.	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries