

Tigard Police Dept

City of Tigard

Wash_pol06A

Building Type		County	
Police - City		Washington	
Street			
13125 Sw Hall Blvd			
City	State	Zip	
Tigard	OR	97223	
Latitude		Longitude	
45.42521		122.76738	
Tracking Code		Inspection Date	
RVS in 2006		6/29/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Tertiary		0	0	0	0	0	0	0	0	0

Tigard Police Dept

Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	Differential Settlement with Damage
None	None
None	None



SE Plan Irregularity Primary

NE Secondary Structural Type
signs of woodpeckers....W2?

NW General Site

SE Plan Irregularity Primary
RM1 walls

NW Vertical Irregularity Primary



SW Poor Condition