

# Sheriffs Office at City Hall

Washington County

Wash\_pol15A

Building Type Police - County	County Washington	
Street 100 S Main St		
City Banks	State OR	Zip 97106
Latitude 45.6195	Longitude 123.1142	
Tracking Code RVS in 2006	Inspection Date 7/7/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	0	-0.2	0	0	-0.6	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sheriffs Office at City Hall

## Final RVS Score

Final Type	Final Score
URM	0

## FEMA-154 Collapse Potential

Very High (100%)



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Sheriffs Office at City Hall

Wash\_pol15A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1910
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Other: Brick Veneer		None	
Unreinforced Chimneys		None	
None		None	
			
W Primary Structural Type second layer of brick just visible near window frame.		NW Falling Hazard	
		N General Site	
		NE General Site	
		E Primary Structural Type older URM on left.	
		NE General Site	
			
E Falling Hazard		SE Building Name	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries