

Sherwood PD

City of Sherwood

Wash_pol17A

Building Type		County	
Police - City		Washington	
Street			
20495 SW Borchers Dr			
City	State	Zip	
Sherwood	OR	97140	
Latitude		Longitude	
45.36828		122.84991	
Tracking Code		Inspection Date	
RVS in 2006		7/4/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Sherwood PD

Final RVS Score

Final Type

Final Score

RM1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: 2 to 3 Changes
None	None
None	None

Falling Hazards	Poor Conditions
Other: General	None
Parapets: General	None
None	None



SE General Site



NE Elevation View



NW Falling Hazard



NE Falling Hazard