

# David Hill Elementary School

Hillsboro SD 1J

Wash\_sch01A

Building Type	County	
School	Washington	
Street		
440 Se Oak St		
City	State	Zip
Hillsboro	OR	97123
Latitude	Longitude	
45.51819	122.98386	
Tracking Code	Inspection Date	
Structural Engineering Report	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	0	-0.8	0	0.5
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

David Hill Elementary School

## Final RVS Score

Final Type

Final Score

W2

0.5

FEMA-154 Collapse Potential

High (>10%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
332		1948	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33904	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions