

# Whitford Middle School

Beaverton SD 48J

Wash\_sch109A

Building Type		County	
School		Washington	
Street			
7935 Sw Scholls Ferry Rd			
City	State	Zip	
Beaverton	OR	97008	
Latitude	Longitude		
45.46315	122.78208		
Tracking Code	Inspection Date		
Structural Engineering Report	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Whitford Middle School

## Final RVS Score

Final Type

Final Score

PC1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
814		1963	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
122947	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions