

# Echo Shaw Elementary School

Forest Grove SD 15

Wash\_sch17A

Building Type School	County Washington	
Street 914 S Linden St		
City Cornelius	State OR	Zip 97113
Latitude 45.51192	Longitude 123.06184	
Tracking Code RVS in 2006	Inspection Date 7/12/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary	RM1	2.8	-1	-0.5	0	0	-0.4	0	0	0.9
Tertiary		0	0	0	0	0	0	0	0	0

Echo Shaw Elementary School

## Final RVS Score

Final Type	Final Score
W2	0.9

## FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Echo Shaw Elementary School

Wash\_sch17A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built			
449	1975	1975	1970			
Total Area (square ft)	Number of Stories	Basement	Pounding Potential			
53684	1	No	Yes			
Plan Irregularities		Vertical Irregularities				
Reentrant Corners: Other		Steps in Elevation View: Very Irregular Changes				
None		None				
None		None				
Falling Hazards		Poor Conditions				
None		None				
None		None				
None		None				
			SE General Site	E Field Verified Year Built	SE Primary Structural Type	
				NW General Site	NW Secondary Structural Type RM1 block on left.	N General Site
				NE General Site	W General Site	NE General Site



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

# Echo Shaw Elementary School

Wash\_sch17A



N General Site



E General Site



NE General Site



# OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries