

# West Union Elementary School

Hillsboro SD 1J

Wash\_sch20A

Building Type		County	
School		Washington	
Street			
23870 Nw West Union Rd			
City	State	Zip	
Hillsboro	OR	97124	
Latitude		Longitude	
45.57705		122.92363	
Tracking Code		Inspection Date	
Already Retrofitted		9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Union Elementary School

## Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

Moderate (>1%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
349		1948	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
42757	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions