

Dilley Elementary School

Forest Grove SD 15

Wash_sch24A

Building Type		County	
School		Washington	
Street			
4115 Sw Dilley Rd			
City	State	Zip	
Forest Grove	OR	97116	
Latitude		Longitude	
45.49016		123.12746	
Tracking Code		Inspection Date	
RVS in 2006		7/13/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dilley Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
250		1942	1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33112	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	Steps in Elevation View: Very Irregular Changes
Reentrant Corners: Other (Adjacent Build/Entity)	Building On Hill or Sloped Site
None	Steps in Elevation View: Single Change (Adjacent Building/Entity)

Falling Hazards	Poor Conditions
Other: Ornamental Hazard Over Exit	None
None	None
None	None



NW General Site



W General Site



S Primary Structural Type


N Pounding Potential
Bldg B on left and Bldg A on right


S General Site



NW Falling Hazard



W General Site

Dilley Elementary School

Forest Grove SD 15

Wash_sch24B

Building Type		County	
School		Washington	
Street			
4115 Sw Dilley Rd			
City	State	Zip	
Forest Grove	OR	97116	
Latitude		Longitude	
45.49016		123.12694	
Tracking Code		Inspection Date	
RVS in 2006		7/13/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dilley Elementary School

Final RVS Score

Final Type

Final Score

W2

0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
250		1942	1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
33112	1	No	Yes

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other (Adjacent Build/Entity)	Steps in Elevation View: Single Change (Adjacent Building/Entity)
None	None
None	None

Falling Hazards	Poor Conditions
None	None
None	None
None	None



S General Site



NW Primary Structural Type



NW General Site