

Joseph Gale Elementary School

Forest Grove SD 15

Wash_sch26A

Building Type	County
School	Washington
Street	
3130 18th Ave	
City	State Zip
Forest Grove	OR 97116
Latitude	Longitude
45.5165	123.09248
Tracking Code	Inspection Date
RVS in 2006	7/12/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	0	-0.4	0	0	0.9
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Joseph Gale Elementary School

Final RVS Score

Final Type	Final Score
W2	0.9

FEMA-154 Collapse Potential

High (>10%)



OregonGeology

Joseph Gale Elementary School

Wash_sch26A



NW General Site



NW Pounding Potential



SW General Site



W Falling Hazard



NW Falling Hazard
weak connection



W General Site



W General Site



N Primary Structural Type
Wood



NE Vertical Irregularity Primary



W Pounding Potential



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Joseph Gale Elementary School

Wash_sch26A

Enrollment 296	Year Built (Field Verified) 1954	Year Built (Alt. Source) 1954	Est. Decade Built 1960
Total Area (square ft) 37487	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: Other None None		Vertical Irregularities Steps in Elevation View: Single Change None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
W General Site	NW General Site	N General Site	
			
SE General Site	N Primary Structural Type	SW General Site	
			
S General Site	SE General Site	SE Pounding Potential	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries