

# Greenway Elementary School

Beaverton SD 48J

Wash\_sch48A

Building Type	County	
School	Washington	
Street		
9150 Sw Downing Dr		
City	State	Zip
Beaverton	OR	97008
Latitude	Longitude	
45.45371	122.80197	
Tracking Code	Inspection Date	
Already Retrofitted	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	-0.5	0	0	-0.4	0	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Greenway Elementary School

## Final RVS Score

Final Type

Final Score

PC1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
429		1979	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
59912	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions