

# Raleigh Hills Elementary School

Beaverton SD 48J

Wash\_sch60A

Building Type		County	
School		Washington	
Street			
5225 Sw Scholls Ferry Rd			
City	State	Zip	
Portland	OR	97225	
Latitude	Longitude		
45.4823	122.75833		
Tracking Code	Inspection Date		
Structural Engineering Report	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	C2	2.8	-1	-0.5	-1	0	-0.4	0	0	-0.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Raleigh Hills Elementary School

## Final RVS Score

Final Type

Final Score

C2

-0.1

FEMA-154 Collapse Potential

Very High (100%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
407		1927	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
60550	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions