

Nancy Ryles Elementary School

Beaverton SD 48J

Wash_sch90A

Building Type	County
School	Washington
Street	
10250 SW Cormorant Dr	
City	State Zip
Beaverton	OR 97007
Latitude	Longitude
45.44513	122.8433
Tracking Code	Inspection Date
Structural Engineering Report	9/15/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Nancy Ryles Elementary School

Final RVS Score

Final Type	Final Score
W2	3.7

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Nancy Ryles Elementary School

Wash_sch90A

Enrollment 662	Year Built (Field Verified) 1991	Year Built (Alt. Source) 1991	Est. Decade Built
Total Area (square ft) 69325	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	