

Mitchell School

Mitchell SD 55

Whee_sch02A

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Wheeler | |
| Street 340 SE High Street | | |
| City Mitchell | State OR | Zip 97750 |
| Latitude 44.56417 | Longitude 120.14673 | |
| Tracking Code RVS in 2006 | Inspection Date 7/26/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | -3 | -0.5 | 0 | 1.6 | -0.8 | 0 | 0 | 2.1 |
| Secondary | RM1 | 3.6 | -2 | -0.5 | 0 | 0 | -0.8 | 0 | 0 | 0.3 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Mitchell School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| RM1 | 0.3 |

FEMA-154 Collapse Potential

High (>10%)

No
Planview
Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mitchell School

Whee_sch02A

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 64 | Year Built (Field Verified) 1983 | Year Built (Alt. Source) 1980 | Est. Decade Built 1980 |
| Total Area (square ft) 12500 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities Reentrant Corners: Other None None | | Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None | |
| Falling Hazards None None None | | Poor Conditions None None None | |
|  | |  | |
| E Building Name | | SW Plan Irregularity Primary | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mitchell School

Mitchell SD 55

Whee_sch02B

| | |
|--------------------|-----------------|
| Building Type | County |
| School | Wheeler |
| Street | |
| 340 SE High Street | |
| City | State Zip |
| Mitchell | OR 97750 |
| Latitude | Longitude |
| 44.56495 | 120.15335 |
| Tracking Code | Inspection Date |
| RVS in 2006 | 7/26/2006 |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W2 | 4.8 | 0 | 0 | 0 | 0 | -0.8 | 0 | 0 | 4 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Mitchell School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W2 | 4 |

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mitchell School

Whee_sch02B

| | | | |
|--|-------------------------------------|---|---------------------------|
| Enrollment 64 | Year Built (Field Verified) 1983 | Year Built (Alt. Source) 1983 | Est. Decade Built 1950 |
| Total Area (square ft) 12500 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards Unreinforced Chimneys None None | | Poor Conditions Other None None | |
|  | |  | |
| S Elevation View | | W Falling Hazard | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mitchell School

Mitchell SD 55

Whee_sch02C

| | | |
|------------------------------|------------------------------|--------------|
| Building Type School | County Wheeler | |
| Street 340 SE High Street | | |
| City Mitchell | State OR | Zip 97750 |
| Latitude 44.56492 | Longitude 120.15367 | |
| Tracking Code RVS in 2006 | Inspection Date 7/26/2006 | |



Seismicity Zone: Moderate

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | W1 | 5.2 | 0 | 0 | 0 | 0 | -0.2 | 0 | 0 | 5 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Mitchell School

Final RVS Score

| Final Type | Final Score |
|------------|-------------|
| W1 | 5 |

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



Oregon Geology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Mitchell School

Whee_sch02C

| | | | |
|---|-------------------------------------|---|---------------------------|
| Enrollment 64 | Year Built (Field Verified) 1983 | Year Built (Alt. Source) 1983 | Est. Decade Built 1950 |
| Total Area (square ft) 12500 | Number of Stories 1 | Basement | Pounding Potential No |
| Plan Irregularities None None None | | Vertical Irregularities None None None | |
| Falling Hazards None None None | | Poor Conditions Other None None | |
|  NW General Site | | | |



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries