

# Amity Police and Fire Dept

City of Amity

Yamh\_fir01A

Building Type	County
Fire - City	Yamhill
Street	
401 Trade St	
City	State Zip
Amity	OR 97101
Latitude	Longitude
45.11657	123.20581
Tracking Code	Inspection Date
RVS in 2006	8/10/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Amity Police and Fire Dept

## Final RVS Score

Final Type	Final Score
RM1	1.7

## FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

# Amity Police and Fire Dept

Yamh\_fir01A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1960
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Torsion: Eccentric Stiffness		None	
Reentrant Corners: L Shaped		None	
None		None	
Falling Hazards		Poor Conditions	
Other: General		None	
None		None	
None		None	
			
NE Primary Structural Type	N Elevation View	NW Elevation View	
			
W Plan Irregularity Primary	SW Elevation View	SE Elevation View	
			
N Falling Hazard	NE Falling Hazard	SE Falling Hazard	
			
N Falling Hazard	NE Falling Hazard	SE Falling Hazard	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries



N Falling Hazard



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries