

West Valley Fire District

West Valley Fire District

Yamh_fir05A

Building Type Fire - RFPD	County Yamhill	
Street 825 Ne Main St		
City Willamina	State OR	Zip 97396
Latitude 45.08139	Longitude 123.47641	
Tracking Code New Building	Inspection Date 8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W2	3.8	-2	-0.5	0	2.4	0	0	0	3.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Valley Fire District

Final RVS Score

Final Type	Final Score
W2	3.7

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

West Valley Fire District

Yamh_fir05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2001	2001	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:T shaped (Adjacent Build/Entity)		Steps in Elevation View: Single Change	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
NE	Vertical Irregularity Primary	NE	Building Name
		W Plan Irregularity Primary	
		W General Site	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

West Valley Fire District

West Valley Fire District

Yamh_fir05B

Building Type Fire - RFPD	County Yamhill	
Street 825 Ne Main St		
City Willamina	State OR	Zip 97396
Latitude 45.0813	Longitude 123.47667	
Tracking Code New Building	Inspection Date 8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	2.8	0	0	0	5.1
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

West Valley Fire District

Final RVS Score

Final Type	Final Score
RM1	5.1

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

West Valley Fire District

Yamh_fir05B

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	2001	2001	2000
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners:T shaped (Adjacent Build/Entity)		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
None		None	
None		None	
None		None	
			
SW Elevation View		E Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries