

McMinnville Fire Department

City of McMinnville

Yamh_fir06A

Building Type		County	
Fire - City		Yamhill	
Street			
175 E 1st St			
City	State	Zip	
McMinnville	OR	97128	
Latitude		Longitude	
45.20898		123.19839	
Tracking Code		Inspection Date	
RVS in 2006		8/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	-0.5	0	0	0	-0.6	0	1.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

McMinnville Fire Department

Final RVS Score

Final Type

Final Score

RM1

1.7

FEMA-154 Collapse Potential

Moderate (>1%)



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

McMinnville Fire Department

Yamh_fir06A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
	1987	1987	1980
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No

Plan Irregularities	Vertical Irregularities
Reentrant Corners: Other	None
Torsion: Eccentric Stiffness	None
None	None

Falling Hazards	Poor Conditions
Other: Brick Veneer	None
None	None
None	None



W Field Verified Year Built
1988



SE Elevation View



N Plan Irregularity Primary




NE Elevation View



W Plan Irregularity Primary



NW Plan Irregularity Secondary



SW Primary Structural Type



NW Elevation View



SW Elevation View



W Elevation View

