

# Willamina Police Dept

City of Willamina

Yamh\_pol04A

Building Type Police-City	County Yamhill	
Street 411 Ne C St		
City Willamina	State OR	Zip 97396
Latitude 45.08099	Longitude 123.48604	
Tracking Code RVS in 2006	Inspection Date 8/10/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	W1	4.4	0	0	0	0	0	0	0	4.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Willamina Police Dept

## Final RVS Score

Final Type	Final Score
W1	4.4

## FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

# Willamina Police Dept

Yamh\_pol04A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1950
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	2	No	No
Plan Irregularities		Vertical Irregularities	
Reentrant Corners: L Shaped		None	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Other: General		None	
None		None	
			
W	Elevation View	W	Falling Hazard
			
E	Elevation View		
			
S	Falling Hazard	SE	Primary Structural Type Wood



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries