

Building Type Police-City	County Yamhill
Street 205 N Maple St	
City Yamhill	State OR
Latitude 45.34059	Longitude 123.18753
Tracking Code RVS in 2006	Inspection Date 8/21/2006



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	0	0	-1	0	-0.4	0	0	1.4
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Yamhill Police Dept

## Final RVS Score

Final Type	Final Score
RM1	1.4

## FEMA-154 Collapse Potential

Moderate (&gt;1%)

No  
Planview  
Available



OregonGeology

# Yamhill Police Dept

Yamh\_pol05A

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
			1940
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
	1	No	No
Plan Irregularities		Vertical Irregularities	
None		Building On Hill or Sloped Site	
None		None	
None		None	
Falling Hazards		Poor Conditions	
Unreinforced Chimneys		None	
Parapets: General		None	
None		None	
			
SW Elevation View		SW Elevation View	
			
S Primary Structural Type		S Primary Structural Type	
			
SE General Site		SE Falling Hazard	
		NE Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries