

# Dundee Elementary School

Newberg SD 29J

Yamh\_sch04A

Building Type	County	
School	Yamhill	
Street		
140 Sw 5th		
City	State	Zip
Dundee	OR	97115
Latitude	Longitude	
45.28037	123.00993	
Tracking Code	Inspection Date	
Missed	9/15/2006	



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Dundee Elementary School

## Final RVS Score

Final Type

Final Score

FEMA-154 Collapse Potential

High (>10%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
388		1937	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
49712		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions