

Cook Elementary School

Yamh_sch10A

McMinnville SD 40

| | | | |
|-------------------------------|-------|-----------------|--|
| Building Type | | County | |
| School | | Yamhill | |
| Street | | | |
| 800 Lafayette Ave | | | |
| City | State | Zip | |
| McMinnville | OR | 97128 | |
| Latitude | | Longitude | |
| 45.21207 | | 123.18781 | |
| Tracking Code | | Inspection Date | |
| Structural Engineering Report | | 9/15/2006 | |



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

| | Type | Basic Score | Vert Irreg | Plan Irreg | Pre-Code | Post-Bench | Soil C | Soil D | Soil E | RVS Score |
|-----------|------|-------------|------------|------------|----------|------------|--------|--------|--------|-----------|
| Primary | URM | 1.8 | -1 | -0.5 | -0.2 | 0 | 0 | -0.6 | 0 | -0.5 |
| Secondary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Tertiary | | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |

Cook Elementary School

Final RVS Score

Final Type

Final Score

URM

-0.5

FEMA-154 Collapse Potential

Very High (100%)

No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

| | | | |
|------------------------|-----------------------------|--------------------------|--------------------|
| Enrollment | Year Built (Field Verified) | Year Built (Alt. Source) | Est. Decade Built |
| 330 | | 1929 | |
| Total Area (square ft) | Number of Stories | Basement | Pounding Potential |
| 27138 | 1 | No | No |

| | |
|---------------------|-------------------------|
| Plan Irregularities | Vertical Irregularities |
| | |
| | |
| | |

| | |
|-----------------|-----------------|
| Falling Hazards | Poor Conditions |
| | |
| | |
| | |

