

# Wascher Elementary School

McMinnville SD 40

Yamh\_sch13A

Building Type		County	
School		Yamhill	
Street			
986 7th St Ext			
City	State	Zip	
Lafayette	OR	97127	
Latitude	Longitude		
45.24685	123.10648		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Wascher Elementary School

## Final RVS Score

Final Type

Final Score



## FEMA-154 Collapse Potential

Low (<1%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
318		1997	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
54507	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions