

McMinnville High School

Yamh_sch15A

McMinnville SD 40

Building Type		County	
School		Yamhill	
Street			
615 E 15th St			
City	State	Zip	
McMinnville	OR	97128	
Latitude	Longitude		
45.21941	123.19318		
Tracking Code	Inspection Date		
Structural Engineering Report	9/15/2006		



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	URM	1.8	-1	-0.5	0	0	0	-0.6	0	-0.3
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

McMinnville High School

Final RVS Score

Final Type

Final Score

URM

-0.3

FEMA-154 Collapse Potential

Very High (100%)

**No
Planview
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
1839		1945	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
216884	1	No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions