

Faulconer-Chapman School

Sheridan SD 48J

Yamh_sch16A

Building Type	County	
School	Yamhill	
Street		
332 Sw Cornwall St		
City	State	Zip
Sheridan	OR	97378
Latitude	Longitude	
45.09226	123.40077	
Tracking Code	Inspection Date	
RVS in 2006	8/10/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	PC1	2.6	0	0	0	0	0	0	0	2.6
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Faulconer-Chapman School

Final RVS Score

Final Type	Final Score
PC1	2.6

FEMA-154 Collapse Potential

Low (<1%)



OregonGeology

Faulconer-Chapman School

Yamh_sch16A

Enrollment 617	Year Built (Field Verified) 1949	Year Built (Alt. Source) 1949	Est. Decade Built 1970
Total Area (square ft)	Number of Stories 1	Basement	Pounding Potential Yes
Plan Irregularities Reentrant Corners: T shaped None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
 NE Elevation View		 N Pounding Potential	
 SE Vertical Irregularity Primary		 NW Primary Structural Type	
 SW Elevation View		 W Elevation View	
 N Falling Hazard		 NE Plan Irregularity Primary	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries