

Duniway Middle School

McMinnville SD 40

Yamh_sch20A

Building Type	County	
School	Yamhill	
Street		
575 Michelbook Ln		
City	State	Zip
McMinnville	OR	97128
Latitude	Longitude	
45.21216	123.20986	
Tracking Code	Inspection Date	
New Building	9/15/2006	



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Duniway Middle School

Final RVS Score

Final Type	Final Score
<input type="text"/>	<input type="text"/>

FEMA-154 Collapse Potential

Low (<1%)

No
Planview
Available



OregonGeology

Duniway Middle School

Yamh_sch20A

Enrollment 647	Year Built (Field Verified) 1997	Year Built (Alt. Source) 1997	Est. Decade Built
Total Area (square ft) 81860	Number of Stories	Basement	Pounding Potential No
Plan Irregularities		Vertical Irregularities	
Falling Hazards		Poor Conditions	
			
S General Site Yamh_sch20b		S General Site yamh_sch20c	
			
S General Site Yamh_sch20E		S General Site Yamh_sch20F	
			
S General Site Yamh_sch20G		S General Site Yamh_sch20H	
			
S General Site Yamh_sch20J			



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries