

# Grandhaven Elementary School

McMinnville SD 40

Yamh\_sch23A

Building Type		County	
School		Yamhill	
Street			
3200 Ne Mcdonald Ln			
City	State	Zip	
McMinnville	OR	97128	
Latitude	Longitude		
45.23243	123.1864		
Tracking Code	Inspection Date		
New Building	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Grandhaven Elementary School

## Final RVS Score

Final Type

Final Score



FEMA-154 Collapse Potential

Low (<1%)

# No Planview Available



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
622		1999	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
69000		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions