


# Columbus Elementary School

Yamh\_sch26A

McMinnville SD 40

Building Type		County	
School		Yamhill	
Street			
1600 Sw Fellows			
City	State	Zip	
McMinnville	OR	97128	
Latitude	Longitude		
45.20029	123.21735		
Tracking Code	Inspection Date		
Missed	9/15/2006		



Seismicity Zone: High

## FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary		0	0	0	0	0	0	0	0	0
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Columbus Elementary School

## Final RVS Score

Final Type

Final Score

--	--

FEMA-154 Collapse Potential

Low (<1%)

**No  
Planview  
Available**



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment  
Oregon Department of Geology and Mineral Industries

Enrollment	Year Built (Field Verified)	Year Built (Alt. Source)	Est. Decade Built
539		1993	
Total Area (square ft)	Number of Stories	Basement	Pounding Potential
69600		No	No

Plan Irregularities	Vertical Irregularities

Falling Hazards	Poor Conditions