

Amity High School

Amity SD 4J

Yamh_sch29A

Building Type	County
School	Yamhill
Street	
503 Oak Ave	
City	State Zip
Amity	OR 97101
Latitude	Longitude
45.11656	123.20293
Tracking Code	Inspection Date
RVS in 2006	8/14/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0


Amity High School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential


High (>10%)



OregonGeology

Amity High School

Yamh_sch29A

Enrollment 306	Year Built (Field Verified) 1965	Year Built (Alt. Source) 1965	Est. Decade Built 1960
Total Area (square ft) 50797	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) Reentrant Corners: T shaped None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards Other: General None None		Poor Conditions None None None	
			
SW General Site	NW General Site New bldg.	SW General Site	
			
SW Elevation View new bldg on right	NE Elevation View	W Falling Hazard	
			
W Field Verified Year Built 1965	NW Elevation View	NW Elevation View	




OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Amity High School

Yamh_sch29A



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries

Amity High School

Amity SD 4J

Yamh_sch29B

Building Type	County
School	Yamhill
Street	
503 Oak Ave	
City	State Zip
Amity	OR 97101
Latitude	Longitude
45.11668	123.20231
Tracking Code	Inspection Date
RVS in 2006	8/14/2006



Seismicity Zone: High

FEMA 154 Rapid Visual Screening Score Card

	Type	Basic Score	Vert Irreg	Plan Irreg	Pre-Code	Post-Bench	Soil C	Soil D	Soil E	RVS Score
Primary	RM1	2.8	-1	-0.5	0	0	0	-0.6	0	0.7
Secondary		0	0	0	0	0	0	0	0	0
Tertiary		0	0	0	0	0	0	0	0	0

Amity High School

Final RVS Score

Final Type	Final Score
RM1	0.7

FEMA-154 Collapse Potential

High (>10%)



Amity High School

Yamh_sch29B

Enrollment 306	Year Built (Field Verified) 1965	Year Built (Alt. Source) 1965	Est. Decade Built 1960
Total Area (square ft) 50797	Number of Stories 1	Basement	Pounding Potential No
Plan Irregularities Reentrant Corners:Other (Adjacent Build/Entity) None None		Vertical Irregularities Steps in Elevation View: 2 to 3 Changes (Adjacent Building/Entity) None None	
Falling Hazards None None None		Poor Conditions None None None	
			
NW Elevation View	NE Elevation View	E Elevation View	



OregonGeology

Rapid Visual Screening - Senate Bill #2 - Seismic Needs Assessment
Oregon Department of Geology and Mineral Industries