

## WHAT ARE THE INSPECTORS FINDING?

The inspectors are routinely out in the field conducting inspections. Below are just some of the violations that we have been finding.

Enforcements have been brought against drillers for some of these violations.



Figure 1. Perfs above ground?



Figure 2. Cement bag seal?



Figure 3. Surface casing left in ground.



Figure 4. Old well with bad seal.



Figure 5. Surface casing left in ground and no seal.



Figure 6. Bad seal!



Figure 7. Tag attached with electrical tape.



Figure 8. Destroyed casing.



Figure 9. Abandonment with Slumping Seal.



Figure 10. Monitoring well that had been buried in a parking lot.



Figure 11. Large void found in well seal.



**Figure 12. Bentonite bag seal.**



**Figure 13. Surface casing left in ground and void in seal.**



**Figure 14. Damaged well at construction site.**

**REGION OFFICE PHONE / FAX #'S**

Northwest	ph (503) 986-0900 fax (503) 986-0904
Southwest	ph (541) 471-2886 fax (541) 471-2876
South Central	ph (541) 388-6669 fax (541) 388-5101
North Central	ph (541) 278-5456 fax (541) 278-0287
East	ph (541) 523-8224 fax (541) 523-7866

\*\*\*\*\*

**ENFORCEMENT STAFF  
DIRECTORY**

Juno Pandian, Manager  
[juno.g.pandian@wrд.state.or.us](mailto:juno.g.pandian@wrд.state.or.us)  
 (503) 986-0852

Kristopher Byrd, Well  
 Construction Program Coordinator  
[kristopher.r.byrd@wrд.state.or.us](mailto:kristopher.r.byrd@wrд.state.or.us)  
 (503) 986-0851

Tracy Eichenlaub, License and  
 Compliance Officer  
[tracy.l.eichenlaub@wrд.state.or.us](mailto:tracy.l.eichenlaub@wrд.state.or.us)  
 (503) 986-0856

Laurie Norton, Well Log Reviews  
[laurie.k.norton@wrд.state.or.us](mailto:laurie.k.norton@wrд.state.or.us)  
 (503) 986-0850

Janet Halladey, Well  
 Identification  
[janet.l.halladey@wrд.state.or.us](mailto:janet.l.halladey@wrд.state.or.us)  
 (503) 986-0854

Enforcement Fax  
 (503) 986-0902