


Dresser Atlas
DIFFERENTIAL TEMPERATURE LOG



FILE NO. _____ COMPANY GEO OPERATOR CORP / CMC
 WELL N-5
 FIELD MERRERY
 COUNTY DESSOLES STATE OR.
 LOCATION: 3000' S & 315' W OF NE CORNER OF
 OTHER SERVICES TEL./GR BR./MC PARC

PERMIT DRUM CL _____ TWP 22S RGE 12E
 LOGGING MEASURED FROM CL _____ ELEV. 5880'
 DRILLING MEASURED FROM CL _____ FT. ABOVE P.D. OF CL. 5880'

DATE 8/5/87
 SERVICE NUMBER 14854
 DEPTH-DRILLER 3230
 DEPTH-LOGGER 2735
 TOP LOGGED INTERVAL 59' B 415'
 BOTTOM LOGGED INTERVAL 2735' B
 DRILLING - LOGGER 4

BL / SIZE	3 1/2"	3 1/2"
BL / WEIGHT	117 LB	117 LB
DENSITY / VISCOSITY	-	-
PH / FLUID LOSS	-	-
SOURCE OF SAMPLE	-	-
RW / RT MENS. TEMP.	B	B
RWC / RT MENS. TEMP.	B	B
SOURCE OF RW / RWC	B	B
RW / RT BH	B	B
TIME SINCE CIRCULATION	34 HRS	
TIME SINCE DEPTH LOG	14 HRS	
EQUIP. NO. / LOC.	14 1486 / SRC	
RECORDED BY	B. HELD	
ATTENDED BY	MR. HARVEY	

IN MAKING INTERPRETATIONS OF LOGS OUR EMPLOYEES WILL GIVE CUSTOMER THE BENEFIT OF THEIR BEST JUDGMENT, BUT SINCE ALL INTERPRETATIONS ARE OPINIONS BASED ON INTERFERENCES FROM ELECTRICAL OR OTHER MEASUREMENTS, WE CANNOT AND WE DO NOT GUARANTEE THE RELIABILITY OR ACCURACY OF THESE INTERPRETATIONS. SERVICE EMPLOYEES OR CLIENTS ARE RESPONSIBLE FOR ANY LOSS, DAMAGE, OR EXPENSES INCURRED BY THE CUSTOMER RESULTING FROM ANY INTERPRETATION MADE BY ANY OF OUR EMPLOYEES.

REMARKS RUN (1)
 RODS STUCK IN HOLE UP TO APPROX 2689'

EQUIPMENT DATA

RUN	TRIP	TOOL	SERIAL NO.	SERIES NO.	POSITION
1	1	TEMP	51989	2120	FREE
1	1	CCL			

WELL NAME: N-5 FILE: 1 DATE: 88/05/87 TRIP: 1 TIME: 15:10:07
 SERVICE: KC408A REVISION: FSYSAL REV 0088 VER 1 DOWN MODE: RECORD

