

STATE OF OREGON
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
1069 State Office Building, Portland 1, Oregon

WELL SUMMARY REPORT
(Submit in duplicate)

Operator Ross Mitchell Field Dallas Area
Well No. Bliven - Adams #4 SW1/4 Sec. 10, T 8S, R 5W, WM W. B. & M.
Location _____ Elevation above sea level _____ feet
All depth measurements taken from top of _____, which is _____ feet above ground

In compliance with the rules and regulations pursuant to ORS 520 (Chapter 667 OL 1953) the information given herewith is a complete and correct record of the present condition of the well and all work done thereon, so far as can be determined from all available records.

Date July 1960 Signed R.R. Mitchell
Title Operator

Engineer or Geologist Superintendent (President, Secretary or Agent)

Commenced drilling 1960 Completed drilling 1960 Drilling tools Cable Rotary
Total depth 340' Plugged depth 0 GEOLOGICAL MARKERS DEPTH
Junk Spencer Em. 0-340'

Commenced producing _____ Date _____ Flowing/gas lift/pumping (cross out unnecessary words)

	Clean oil bbl. per day	Gravity Clean oil	Percent water including emulsion	Gas Mcf. per day	Tubing Pressure	Casing Pressure
Initial production						
Production after 30 days						

CASING RECORD (Present Hole)

Size of casing (A.P.L.)	Depth of shoe	Top of casing	Weight of casing	New or second hand	Seamless or Lapweld	Grade of casing	Size of hole drilled	No. of sacks of cement	Depth of cementing if through perforations
8"	50'	0	(0.25 wall)				12"	12 sacks	Around Shoe
5"	305'	0	(5" casing pulled on abandonment)						

PERFORATIONS

Size of casing	From	To	Size of perforations	Number of rows	Distance between centers	Method of perforations
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				

WJM