



COMPANY STANDARDS OIL CO. OF CALIF.
WESTERN OPERATIONS INC.

WE. BLUE MOUNTAIN UNIT NO.1

CLASSIFIED BLUE MOUNTAIN AREA

VALHEER STATE OREGON

2430 N.E. 2206 E. FROM S.W. COR. SEC. 34

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

34 Twp. 37 S. R. 7 S. E. 91

BORE HOLE RECORD				CASING RECORD			
Csg. Size	From	To	Wt.	From	To	Centralized Interval	Open Perforations
15"	7	2015'	10 3/4"	45'	0	2015'	
9 7/8"	2015'						

SERVICE TICKET NO. 67811 REMARKS:
 CEMENT - BOTTOM STAGE: 1056 CU FT 1:1 MIX W/ 4% GEL & 2% CAP. FOLLOWED BY 650 SKS CLASS "A" W/ LAST 300 SKS 3% GEL. LOST CIRCULATION WHILE PUMPING.
 TOP SQUEEZE BELOW B.O.P. 200 SKS CLASS "G" W/ 2% GEL. LOST C.I.P. 4:30 AM. 7-4-73

WELIX does not guarantee the accuracy of any interpretation of log data, conversion of log data to physical rock parameters, or recommendations which may be given by WELIX personnel or which may appear on the log or on any other form. Any user of log data, interpretations, conversions, or recommendations agrees that WELIX is not responsible, except where due to gross negligence or willful misconduct, for any loss, damages, or expenses resulting from the use thereof.

COLLAR LOG
 - GAMMA -
 - ARI Gamma-Ray Unit -
 - NEUTRON -
 - ARI NEUTRON UNIT -

