

STATE OF OREGON
DEPARTMENT OF GEOLOGY AND MINERAL INDUSTRIES
1069 State Office Building, Portland 1, Oregon

WELL SUMMARY REPORT
(Submit in duplicate)

Operator Seneca Oil & Gas Develop Field Izee Area
Well No. Lemmons 1 NE1/4 Sec. 18, T 17S, R 29E, WM W. B. & M.
Location _____ Elevation above sea level 2000'+ feet

All depth measurements taken from top of _____, which is _____ feet above ground

In compliance with the rules and regulations pursuant to ORS 520 (Chapter 667 OL 1953) the information given herewith is a complete and correct record of the present condition of the well and all work done thereon, so far as can be determined from all available records.

Date 1957 Signed W.J. Griffith

Engineer or Geologist Superintendent Title President
(President, Secretary or Agent)

Commenced drilling 1956 Completed drilling 1957 Drilling tools Cable
Rotary

Total depth _____ Plugged depth _____ GEOLOGICAL MARKERS DEPTH

Junk _____ Spud in Jurassic

Commenced producing _____ Date _____ Flowing/gas lift/pumping
(cross out unnecessary words)

Initial production
Production after 30 days

Clean oil bbl. per day	Gravity Clean oil	Percent water including emulsion	Gas Mcf. per day	Tubing Pressure	Casing Pressure

CASING RECORD (Present Hole)

Size of casing (A.P.L)	Depth of shoe	Top of casing	Weight of casing	New or sec- ond hand	Seamless or Lapweld	Grade of casing	Size of hole drilled	No. of sacks of cement	Depth of cement- ing if through perforations
10"	160'	0						None	
6"	246'	0						100 sks	

PERFORATIONS

Size of casing	From	To	Size of perforations	Number of rows	Distance between centers	Method of perforations
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				
	ft.	ft.				

Electrical Log Depths _____ (Attach Copy of Log)